

## MCCU REVIEW SUMMARY SHEET

TYPE of REVIEW:
DOT/ICC # 745583 OPERATING AUTHORITY: Interstate Interstate  REVIEW DATES: DATE STARTED 9/18/2006  DATE FINISHED 9/25/2006 TOTAL HOURS 40  ENFORCEMENT RECOMMENDATIONS: If yes list which violations INVESTIGATING OFFICER: Yes No Explain why or why not in "Remarks" area SUPERVISOR YES NO Explain why or why not in "Remarks" area ENFORCEMENT PREAPPROVAL via FMCSA: If yes list which violations in remarks
DATE FINISHED  9/25/2006  TOTAL HOURS  40  ENFORCEMENT RECOMMENDATIONS: If yes list which violations INVESTIGATING OFFICER:  YES NO Explain why or why not in "Remarks" area SUPERVISOR  YES NO Explain why or why not in "Remarks" area ENFORCEMENT PREAPPROVAL via FMCSA: If yes list which violations in remarks
ENFORCEMENT RECOMMENDATIONS: If yes list which violations INVESTIGATING OFFICER: YES NO Explain why or why not in "Remarks" area SUPERVISOR YES NO Explain why or why not in "Remarks" area ENFORCEMENT PREAPPROVAL via FMCSA: If yes list which violations in remarks
INVESTIGATING OFFICER: YES NO Explain why or why not in "Remarks" area SUPERVISOR YES NO Explain why or why not in "Remarks" area ENFORCEMENT PREAPPROVAL via FMCSA: If yes list which violations in remarks
ENFORCEMENT DATES: DATE STARTED
DATE FINISHEDTOTAL HOURS
CHECK if APPLICABLE: ☐ PSC AUTHORITY ☐ PROFILE RAN ☐ COMPLAINT ☐ HM SHIPPER ☐ HM CARRIER ☑ IFTA ☑ IRP☐ DPS AUTHORITY
SAFESTAT LIST: DA DB DC DD DE DHM DBUS DOTHER DSTP SHIPPER LIST
REVIEW RATING: Satisfactory OOS RULE: If applicable 45 DAYS 60 DAYS
REVIEW COPIES: Check when completed FMCSA:
MCC OFFICE: DEMAILED NOTICE TO MCC PART A TO MCC
SAFETY NET: OPY TO TRISH  PSC SC MAIL / DMS
CASE COPIES: Check when completed  FMCSA:
I III COM. DE LOS COMETE LE L'ARTO COM
SAFETY NET: 1 EXPORT TO DISKETTE
SAFETY NET: 1 EXPORT TO DISKETTE ORIGINAL & 1 PAPER COPY
SAFETY NET: 1 EXPORT TO DISKETTE ORIGINAL & 1 PAPER COPY  INVESTIGATOR NAME: Terry W. Harvey STP CODE: SC0036
SAFETY NET: 1 EXPORT TO DISKETTE ORIGINAL & 1 PAPER COPY  INVESTIGATOR NAME: Terry W. Harvey STP CODE: SC0036
SAFETY NET: 1 EXPORT TO DISKETTE ORIGINAL & 1 PAPER COPY  INVESTIGATOR NAME: Terry W. Harvey STP CODE: SC0036
SAFETY NET: 1 EXPORT TO DISKETTE ORIGINAL & 1 PAPER COPY  INVESTIGATOR NAME: Terry W. Harvey STP CODE: SC0036
SAFETY NET: 1 EXPORT TO DISKETTE ORIGINAL & 1 PAPER COPY  INVESTIGATOR NAME: Terry W. Harvey STP CODE: SC0036

South Carolina State Transport Police

**US DOT#** 745583

Legal: PETER WASHINGTON

Operating (DBA): WASHINGTON BUS LINE

MC/MX #: 338234

Review Type: Compliance Review (CR)

Scope:

Principal Office

Federal Tax ID: 248-76-4890 (SSN)

Location of Review/Audit: Company facility in the U. S.

Carrier: Shipper:

Non-HM

Non-HM

N/A

Business: Individual

Gross Revenue: \$60,000.00

for year ending: 12/31/2005

Territory:

Owned Term Leased Trip Leased

Cargo Tank:

N/A

#3 WRIGHT PLACE

HILTON HEAD, SC 29925

**Contact Name:** 

Peter Washington

Phone numbers: (1) 803-681-2924

(2)843-247-7246

Fax 843-342-2302

E-Mail Address:

#3 WRIGHT PLACE HILTON HEAD, SC 29925

Authorized for Hire

Passengers

Does carrier transport placardable quantities of HM? Is an HM Permit required?

Inter

2

Intra

Average trip leased drivers/month: 0

< 100 Miles:

>= 100 Miles:

N/A

**Total Drivers: 2** 

CDL Drivers: 2

Owned Term Leased Trip Leased

Motor Coach

Power units used in the U.S.:1

Percentage of time used in the U.S.:100



U.S. DOT #: 745583

Review Date: 09/21/2006

### Part A

QUESTIONS regarding this report or the Federal Motor Carrier Safety or Hazardous Materials rules may be addressed to the Office of Motor Carriers at:

South Carolina State Transport Police, Motor Carrier Compliance Unit at 10311 Wilson Blvd., PO Box 1993, Blythewood, SC 29016 (803-896-5500)

This report will be used to assess your safety compliance.

Person(s) Interviewed
Name: Peter Washington
Name: Title: Owner
Title:

Reported By: Term Wharry
Title: J.F.

Received By: Let Washington
Title: Code:SC0036 Date:9/21/2006

Received By: Let Washington
Title: Code:SC0036 Date:9/21/2006



U.S. DOT #: 745583

Review Date: 09/21/2006

### **Part B Violations**

1 FEDERAL	Primary: 40.15(d) Secondary: 382.105		Discovered	Checked	1	Vehicles Checked
Example	rvice agent to perform the functions - Alfred Gordon - Trip Date -09/14/20			sentative.	<b>.</b>	· · · · · · · · · · · · · · · · · · ·
2 FEDERAL	Primary: 382.601(a)		Discovered	Checked 1		Vehicles Checked
Example	de educational materials explaining s Washington - Trip Date - 09/14/20		·	•		
3 FEDERAL	Primary: 382.603		Discovered	Checked 1	Drivers/	Vehicles Checked
training for alc <b>Example</b>	ire persons designated to determine ohol and/or 60 minutes of training for as Washington - Trip Date - 09/14/20	r controlled substance	es.		receive 60 n	ninutes
Safety Fitness I Total Mil Recordal	Rating Information: es Operated 100 ole Accidents 0 ole Accidens/Million Miles 0.00		Number of Ve	OOS Vehic hicle Inspecte OS Vehicle (I	ed (CR): 0 MCMIS): 0	
Your proposed	and the matine in .	Rating	Factors	-	Acute Critic	al
roui proposed	safety rating is : SATISFACTORY	Fact Fact Fact	or 1: or 2: or 3: or 4:	S S S S	0 0	0 0 0 0
			or 6:	S	-	-

Corrective actions must be taken for any violations (deficiencies) identified on Part B of this report.



U.S. DOT#: 745583

Review Date: 09/21/2006

## Part B Requirements and/or Recommendations

- 1. Copies of the regulations, forms, interpretations, and manuals are available from a variety of sources. Check the FMCSA website for a current list of suppliers. www.fmcsa.dot.gov/factsfigs/eta/forms.html.
- Conduct periodic internal reviews of your driver qualification, hours of service control, maintenance, accident analysis/reporting, training, and other safety systems to ensure continued compliance with the FMCSR.
- 3. If you have any questions concerning this report,, please contact the Federal Motor Carrier Safety Administration, (... INSERT ADDRESS OF DIVISION OFFICE HERE...)
- 4. Employers are responsible for their officers', employees', agents', consortia, and/or contractors' compliance with the requirements of 49 CFR Parts 40 and 382.
- 5. Review the circumstances under which a CDL is required. CDL and drug testing rules apply to both interstate and intrastate commerce.
- **6.** Ensure that all drivers are fully and properly qualified before operating in interstate commerce. Maintain a complete file as required for each driver, documenting the qualification process.
- 7- Maintain all required controlled substance testing records including yearly summaries, quarterly summaries, test information, test results, records of training etc., as required by 49 CFR Parts 40 and 382 of the FMCSR.
- 8. Require all drivers to prepare complete and accurate records of duty status for each day, and to submit them within 13 days. Maintain all duty status records on file, with all supporting documents, for at least 6 months.
- 9. Ensure that all documents supporting records of duty status (such as toll, fuel repair and other on-the-road expense receipts, as well as invoices, bills of lading, dispatch records, etc.) are kept on file for at least 6 months.
- 10. Obtain from any driver used for the first time (or intermittently) a signed statement showing the total time on-duty during the preceding seven (7) days and the time at which the driver was last relieved from duty.
- 11. Toll receipts and other on-the-road expense receipts, invoices, bills of lading, dispatch records, and other "supporting document" must be kept on file for six (6) months. This requirement also applies to records generated by the use of owner-operators. You may keep legible photocopies in lieu of originals.
- 12. If you want some drivers to use the 100 air-mile radius exemption, make sure that the drivers meet all terms of the exemption, including being released from duty no more than 12 hours from when they report for duty. Logs must be prepared if a driver does not meet the 12 hour requirement.
- 13. Ensure that all drivers' records of duty status (logs) are accurate. Check them against " supporting documents" to verify accuracy. Prohibit falsification of logs by any driver. Review the rules on supporting documents. Take appropriate action against drivers who falsify logs.
- 14. Review with your drivers periodically the procedures for doing pre-trip and post-trip inspections. Ensure that safety defects reported by drivers on their Vehicle Inspection Reports (VIR) are repaired before the vehicle is re-dispatched. Require drivers to prepare Vehicle Inspection Reports on a daily basis. Keep them on file for 90 days.
- 15. Within 15 days, send a letter to the FMCSA describing what actions you have taken in response to this review to ensure you are complying with the Federal Motor Carrier Safety and Hazardous Materials Regulations.



U.S. DOT #: 745583

Review Date: 09/21/2006

### Part B Requirements and/or Recommendations

- 16. This report contains citations of regulations that are deemed serious in nature and could result in penalties against your company and/or your drivers.
- 17. This review will result in a Safety Rating.
- 18. A complete Educational and Technical Assistance package entitled " A MOTOR CARRIER'S GUIDE TO IMPROVING HIGHWAY SAFETY" is available free on the FMCSA website to assist you in complying with the safety regulations. It contains many forms and documents useful for improving the safety of your operations. Check: www.fmcsa.dot.gov/factsfigs/eta/index.html.
- 19. For questions about DOT numbers or biennial updates: 800-832-5660 or 703-280-4001 For questions about licensing, authority or MC numbers: 202-366-9805 For questions about insurance: 202-385-2423 For household goods complaints: 888-DOT-SAFT (888-368-7238)



		South Carolina State Transport Police
US DOT # 745583	Logal. I LILIX	WASHINGTON
	Operating (DB	A):WASHINGTON BUS LINE
MC/MX #: 338234		Federal Tax ID: 248-76-4890 (SSN)
Review Type: Compli		•
	al Office	Location of Review/Audit: Company facility in the U. S. Territory:
Carrier: N Shipper: N Cargo Tank:	on-HM Non-HM /A N/A N/A	Business: Individual Gross Revenue: \$60,000.00 for year ending: 12/31/2005
and the second s		
#3 WRIGHT PLACE HILTON HEAD, SC 2	9925	
Contact Name: Phone numbers: (1 E-Mail Address:	Peter Washington 803-681-2924	(2)843-247-7246 Fax 843-342-2302
#3 WRIGHT PLACE HILTON HEAD, SC 2	9925	
	Report	# of Pages
	Part A - General	2
	Part B - Violations	1
	Part B - Recomme	
	Review/Audit Rec	eipt Page 1
Total Pages		ages 6
the total num	ber of pages indica	acknowledge that I have received a copy of this review/audit and agree with ted (above) for each document. My signature does not imply agreement with however they have been discussed in detail with me.

South Carolina State Transport Police, Motor Carrier Compliance Unit at 10311 Wilson Blvd., PO Box 1993, Blythewood, SC 29016 (803-896-5500)

This report will be used to assess your safety compliance.

PUS	<u> </u>	Inte	LAIGMED	

Name: Peter Washington

Title: Owner

Title:

Reported By:

Name:

Title:

Code: SC0036

Date: 9/21/2006

Received By:

Title:





U.S. DOT #: 745583

Review Date: 09/21/2006

## Safety Fitness Rating Explanation

This report lists the facts which were used to determine the Safety Fitness Rating for the above motor carrier. A check mark identifies the range within which the data fell when determining the Safety Fitness Rating. All information within a FACTOR block relates only to that FACTOR.

FACTOR 1 VIOLATIONS AFFECTIN	General (CFR Parts 387, 390) G RATING POINTS	√ 0 Point = Satisfactory 1 Point = Conditional >1 Point = Unsatisfactory	
NONE	TOTAL POINTS: 0 = SATISFA	ACTORY	
FACTOR 2 VIOLATIONS AFFECTIN		383, 391)   √ 0 Point = Satisfactory 1 Point = Conditional >1 Point = Unsatisfactory  FACTORY	
FACTOR 3 VIOLATIONS AFFECTIN NONE		P2, 395)	
VIOLATIONS AFFECTIN NONE	TOTAL POINTS: 0 =	er than 3 inspections SATISFACTORY	
Fewer than 3 Inspections	3 or more Inspections		
Rate same as other Regulatory Factors 1, 2, and 3	OOS Less than 34%	OOS 34% or Higher	
√ 0 Point = Satisfactory 1 Point = Conditional >1 Point = Unsatisfactory	Satisfactory Conditional  Conditional Unsatisfactory  If a pattern of Non-Compliance with a Critical or an Acute Violation  Satisfactory  Unsatisfactory  If a pattern of Non-Compliance with a Critical or an Acute Violation		
	azardous Material (CFR Parts 397, 171, 172, carrier of Hazardous Material	173, 177, 180)	
FACTOR 6	Accident (Recordable Accident Ra Recordable Accidents) X (1 million)) + (Tot (0 X 1,000,000) + 100 = 0.00 = SATISFACT	al Miles) = Rate	
	ACCIDENT RATE FACTOR RAT  √ 0.000 - 1.500 = Satisfactor  >1.500 = Unsatisfactor	у	
OVERALL SAFETY FITN Number of Factors (1- Unsatisfactory 0	6) shown above as less than satisfactory  Conditional	SATISFACTORY	



U.S. DOT #: 745583

Review Date: 09/21/2006

## Safety Fitness Rating Explanation

## FORMULA TO CALCULATE THE OVERALL SAFETY FITNESS RATING

Number of Factors

	Unsatisfactory	Conditional	OVERALL RATING
1	0	2 or fewer	Satisfactory
	0	3 or more	Conditional
	1	2 or fewer	Conditional
	1	3 or more	Unsatisfactory
	2	0 or more	Unsatisfactory





U.S. DOT #: 745583

Review Date: 09/21/2006

#### Part C

Reason for Review: Company Request

Planned Action:

Compliance Monitoring

Safestat Category:

Parts Reviewed Certification:

178 180 325 382 383 387 390 391 392 393 395 396 397 398 171 172 173 177

✓

**Prior Reviews** 

**Prior Prosecutions** 

### **Unsat/Unfit Information**

Does passenger vehicle transport more than 15 passengers, including driver? Yes - Interstate and Intrastate Does carrier transport placardable quantities of hazardous materials?

Unsat/Unfit rule:45-Day - Interstate Passenger

Corporate Contact: Peter Washington

Corporate Contact Title: Owner

Special Study Information:

#### Remarks:

This investigation was initiated because the carrier had applied to the South Carolina Public Service Commission for a Class C Charter Bus Certificate. This certificate requires that the carrier be in compliance with the Federal Motor Carrier Safety Regulations as adopted by South Carolina. Peter Washington, Owner, requested that an intrastate compliance review be conducted. During the investigation it was determined that the carrier was also an interstate carrier. Peter Washington dba Washington Bus Lines is owned and operated by Peter Washington. He has one 47 passenger Motor Coach and 2 drivers.

Carrier has been in business since 1998, but has not been operating much recently due to health problems and mechanical problems with the bus. All records were kept at his residence and were provided within 48 hours by Mr. Russell and Albert Gordon, a consultant from G.A.L. Safety & Compliance Management, LLC.

In Part 40, carrier had the consultant, Albert Gordon acting as the designated employee representative.

In Part 382, carrier's company policy had Albert Gordon, Consultant as the designated employee representative and Peter Washington, Owner did not have supervisor training for reasonable suspicion testing.

In Part 383, all driver records were checked by CDLIS.

In Part 391, a total of two driver qualification files were checked with no violations.

In Part 393, bus unavailable for inspection.

In Part 395, a total 60 days time cards were checked, with no violations. Carrier is going to use both time cards and log books in the future.

In Part 396, carrier did not have any violations.

Mr. Washington stated that he would correct all violations immediately and Albert Gordon was replaced by Peter Washington as the Designated Employee representative.



U.S. DOT #: 745583

Review Date: 09/21/2006

## Part C

Principal Reviewer Signature		Upload Authorize	ed:	Yes	No
Tenny Hows	SC0036	Authorized by:			Date:
Assistant Reviewers Signature(s)		Uploaded:	Yes	No	Failure Code:
		Verified by:			Date:

U.S. Department of Trust partialists from Mone Corine saletty Administration

#### ENDORSEMENT FOR

Form Approved
OMB No. 2126-0008

# MOTOR CARRIER POLICIES OF INSURANCE FOR PUBLIC LIABILITY UNDER SECTION 18 OF THE BUS REGULATORY REFORM ACT OF 1982

Lasted to PETER WASHINGTON DBA: WASHINGTON BUS LINE	of HILTON HEAD, SC
Onted at LONG BEACH, NEW YORK dis 3R	D day of <u>MAY</u> , 20 <u>06</u>
Amording Policy No. BAIS9621	Effective Date S/3/06
Name of Insurance Company LANCER INSURANCE COMPANY	
Countersigned by	Nous of Rice
• • -	Authorized Company Representative
The policy to which this customerant is attached provides primary or excess insurance	, as indicated by " 🔯 " for the timits shown:
This insurance is principly and the company shall not be liable for amounts in excep-	ss of \$ _5,000,900 for each occident.
This insurance is excess and the company shall not be flable for amounts in excess underlying that of S for each accident.	of\$ for each socident in excess of the
Whenever required by the Federal Moure Carrier Softey Administration (PMCSA), a endorstenests. The dominary also agrees, upon telephone request by an authorized representations number to eathly:  (\$160.431-4481)	the company agrees to furnish the FMCSA a duplicate of said policy and all its enturies of the PMCSA, to verify that the policy is in torce as of a particular date. The
Consellation of this endorsement may be effected by the company or the insural by giving commence from the date the notice is smalled, proof of multing shall be sufficient proof of partialling triiny (30) days notice to the FMCSA (said 30 days notice to commence from the	finatice), and (2) if the insured is subject to the FMCSA's registration requirements, by
DEFINITIONS AS USED IN	THIS ENDORSEMENT
Accident includes continuous or reposted exposure to conditions which results in Public Liability which the insured neither expected for intended.	Mater carrier means a for-thre corrier of powergers by motor vehicle.
Builty Injury menes injury to the body, sickness or disease to any person, including death resulting from any of these.	Property Daniege means daninge to or loss of use of inagible property.  Public Limiting means liability for bodily injury or property damage
The insurance policy to which this endomerant is attached provides automable liability insurance and is amended to assure compliance by the insured, within the limits saved herein, es a fur-hire motor currier of passengers with Section 18 of the Bus Regulatory Reform Act of 1982 and the rules and regulations of the Federal Moore Carrier Saftry Administration.  In consideration of the premoun stated in the volley to which this endomerant is attached, the insurer (the company) agrees to pay, within the limits of liability described herein, any final judgment received against the insured for public liability resulting from negligence in the operation, animenance or use of motor vehicles subject to financial responsibility requirements of Section 18 of the Bus Regulatory Reform Act of 1982 regardless of whether or not each motor vehicle is specifically described in the policy and whether or not such negligence sectus on any nonce of the any terming authorized to be served by the insured or elsewhere. Such manames us is altered, for public liability, does not apply to highly is or death of the insured employees white engages in the dourse of their employment, or property transported by the insured, designated as surge. It is understood and agreed that we company from lability or from the payment of any final judgment, within the limits of liability herein described, irrespective of the financial condition,	However, all terms, conditions, and limitations in the policy to which the endorsement is attached shall remain in full times and effect as similing between the insured and the company. The insured agrees to reinduce the company for any payment made by the company on account of any payment that the company would not have been ubligated to make under the provisions of the policy exacts for the agreement contained in this endorsement.  It is further understood and agreed that, upon failure of the company to pay any final judgment recovered against the insured in provided bettern, the judgment creditor may maintain an ocion in any court of competent jurisdiction against the company to compete such payment.  The finite of the company's liability for the amounts prescribed in this endorsement apply separately to each accident and any payment under the policy because of any one antident shall not operate to reduce the liability of the company for the payment of final judgments resulting from any other addition.

The Bus Regulatory Reform Act of 1982 requires limits of financial responsibility according to vehicle sesting aspective, it is the MOTOR CARRIER'S obligation to obtain the required limits of financial responsibility. THE SCHEDULE OF LIMITS SHOWN ON THE REVERSE SIDE DOES NOT PROVIDE COVERAGE. The limits shown in the schedule are for information purposes only.

Form MCS-98B (6/2003)

(Over) UNIFORM MC 1612d (10-02)